C.L. "BUTCH" OTTER - Governor RICHARD M. ARMSTRONG - Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@dhw.idaho.gov

April 1, 2009

Steve Silberberger, Administrator Seven Oaks Community Homes—Candlewood 3940 West 5<sup>th</sup> Avenue #C Post Falls, Idaho 83854

RE: Seven Oaks Community Homes—Candlewood, provider #13G075

Dear Mr. Silberberger:

This is to advise you of the findings of the Medicaid/Licensure Fire Life Safety Survey, which was concluded at Seven Oaks Community Homes—Candlewood, on March 25, 2009.

Enclosed is your copy of a Statement of Deficiencies/Plan of Correction, form CMS-2567, which states that no Medicaid deficiencies were noted at the time of the survey. Also, enclosed is a similar form stating that no State licensure deficiencies were noted at the time of the survey.

Thank you for the courtesies extended to us during our visit. If we can be of any help to you, please call our office at (208)334-6626.

Sincerely,

TAYLOR BARKLEY Health Facility Surveyor

Jy L BM

Facility Fire Safety and Construction Program

TB/li

Enclosure

## DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

Printed: 03/30/2009 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION  A. BUILDING 02  B. WING		(X3) DATE SURVEY COMPLETED	
	ROVIDER OR SUPPLIER	13G075 Y HOMES - CANDLE	STREET ADD	PRESS, CITY, S ANDLEWO		-   03/2	25/2009
			POST I	FALLS, ID	83854		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K 000	K 000 INITIAL COMMENTS			K 000			
	The building is a 2,000 s.f single story residential structure of Type V(000) (i.e., wood frame construction). Plans were received in the State Survey agency in March of 2004 and the construction of the building was completed in mid May of 2004. The home consists of three (3) resident sleeping rooms, a dining room, living room, two (2) bathrooms, and a double car garage. Fire/life safety features include a modified residential 13d sprinkler system throughout all habitable spaces/closets, a complete fire alarm/smoke detection system throughout, basic battery pack emergency lighting, and two (2) portable ABC fire extinguishers.  The facility was found to be in substantial compliance with applicable fire/life safety requirements during the annual fire/life safety survey conducted on March 25, 2009. The facility was surveyed under the Life Safety Code, 2000 Edition, Chapter 32, New Residential Board & Care Occupancies, Impractical Evacuation Capability in accordance with 42 CFR 483.470 (j).  The survey was conducted by:  Taylor Barkley Health Facility Surveyor Fire/Life Safety and Construction						
LABORATO	 PRY DIRECTOR'S OR PRO	OVIDER/SUPPLIER REPRES	ENTATIVE'S SI	GNATURE	TITLE		(X6) DATE

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

PRINTED: 03/30/2009 FORM APPROVED

**Bureau of Facility Standards** STATEMENT OF DEFICIENCIES (X3) DATE SURVEY (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING 02 B. WING 13G075 03/25/2009 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER SEVEN OAKS COMMUNITY HOMES - CANDLEWOO **4880 CANDLEWOOD** POST FALLS, ID 83854 PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES (X4) ID (EACH CORRECTIVE ACTION SHOULD BE COMPLETE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX PREFIX CROSS-REFERENCED TO THE APPROPRIATE REGULATORY OR LSC IDENTIFYING INFORMATION) DATE TAG TAG DEFICIENCY) M 000 M 000 16.03.11 Inital Comments The building is a 2,000 s.f single story residential structure of Type V(000) (i.e., wood frame construction). Plans were received in the State Survey agency in March of 2004 and the construction of the building was completed in mid May of 2004. The home consists of three (3) resident sleeping rooms, a dining room, living room, two (2) bathrooms, and a double car garage. Fire/life safety features include a modified residential 13d sprinkler system throughout all habitable spaces/closets, a complete fire alarm/smoke detection system throughout, basic battery pack emergency lighting, and two (2) portable ABC fire extinguishers. The facility was found to be in substantial compliance with applicable fire/life safety requirements during the annual Fire/Life Safety survey conducted on March 25, 2009. The facility was surveyed under the LIFE SAFETY CODE, 1976 Edition, Residential Board & Care Occupancies, Impractical Evacuation Capability in accordance with IDAPA 16.03.11 The Survey was conducted by: **Taylor Barkley** Health Facility Surveyor Fire/Life Safety and Construction

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

18SL21

(X6) DATE